

FLUID BED REHABILITATION

PROJECT DATA SHEET

LOCATION

Northeastern US

PROJECT DESCRIPTION

Repairs were needed to an aging fluid bed incinerator. Repairs included installing a new overbed burner system, installing a new furnace skin, repairing the scrubber, as well as replacing the heat exchanger, windbox expansion joint, tuyeres, oil pumps, and electrical instruments. IFCO also coordinated the EPA testing.

IFCO'S ROLE

Engineering assistance, equipment supplier, installation, commissioning

VALUE

\$3 Million

COMPLETED

2013



INDUSTRIAL FURNACE COMPANY

40 Humboldt Street
Rochester, NY 14609

(585) 288 - 2070
www.industrialfurnace.com